

OFFICE OF THE EXECUTIVE ENGINEER R & B DIVISION,  
NABARANGPUR, ODISHA.

No. 3760

Date: 22.10.2021.

To

The Principal,  
Bapuji Public School, Majhiguda  
Nabarangpur.


Sub: **Structural Safety Certificate of Bapuji Public School, Nabarangpur.**

Sir,


With reference to the subject cited above it is to state that, I personally inspected the Bapuji Public School, Majhiguda, Nabarangpur on 18.10.2021 functioning on Khata Number 784/118 that covering Plot No.1473/1478 At Majhiguda, Mouza Padalguda, Nabarangpur and found the building is structurally safe in normal weather condition and structurally fit to run the school.

This certificate is issued for production of the same for official purpose.

Yours Faithfully,

  
Executive Engineer  
Nabarangpur (R&B) Division

  
Manager  
Bapuji Public School  
Nabarangpur

  
Principal  
Bapuji Public School  
Nabarangpur